
2/18







FIG.1






FIG.4





FIG.5






FIG.7




FIG.8A




FIG.8B




FIG.9




FIG.10




FIG.11




FIG.12

:.




FIG.13




FIG.14




FIG.15A




FIG.15B

X-RAY INCIDENT DIRECTION




FIG.16




FIG.17





FIG.18






FIG.20




FIG.21




FIG.22




FIG.23

